





# REDUTORES A ROSCA SEM FIM - DUPLA REDUÇÃO

## FORMAS CONSTRUTIVAS

www.jdaredutores.com.br

|      |      |      |      |      |      |      |      |  |      |      |      |
|------|------|------|------|------|------|------|------|--|------|------|------|
| DS1  | DS2  | DS3  | DS4  | DS5  | DS6  | DS14 | DS15 | DS16   | DS17 | DS18 | DS19 |
| DS20 | DS21 | DS26 | DS27 | DS28 | DS29 | DS34 | DS35 | DS36   | DS37 | DS42 | DS43 |
| DS44 | DS45 | DS50 | DS51 | DS52 | DS53 | DS54 | DS55 | DS62   | DS63 | DS64 | DS65 |
| DV7  | DV8  | DV9  | DV10 | DV11 | DV12 | DV22 | DV24 | DV25   | DV26 | DV30 | DV31 |
| DV32 | DV33 | DV38 | DV39 | DV40 | DV41 | DV46 | DV47 | DV48   | DV49 | DV56 | DV57 |
| DV58 | DV59 | DV60 | DV61 | DV66 | DV67 | DV68 | DV69 | <b>POSIÇÃO PARA BRAÇO DE TORÇÃO</b><br>3AS  3BS  4AS  4BS  |      |      |      |